

Mobile pump station for RIXS HRM

I turned off the mobile turbo station for the HRM. A strange burning smell was coming from the scroll pump. Should be checked. Also vacuum in tank only 2.5×10^{-5} mbar. Did not get worse after the pump was stopped.