

# BPM in EH1

Turned out that the diamond window of the BPM in EH1 was completely gone/broken and therefore it did not work. Boris will replace and bring a new one to the beamline on the 10th of September (Monday)